

# Restoration Details and Additional Photos

## Ground Floor

*Before*



*After*



### N.B.

- All floors and ceilings replaced in 2<sup>nd</sup> house (all existing were cement on wood and rotten)
- The 2<sup>nd</sup> house floor level was lowered
- Windows were enlarged

## ***First Floor***

***Before***



***After***



- Shows floor/ceiling replacement and tiling
- Now level and solid



## ***Taverna***

***Before***



***After***



- The ceiling was replaced
- The floor was leveled and tiled
- A window was opened to the garden



**Garage**

**Before**



**After**



- The largest cellar door was enlarged for the garage door
- The garage was knocked through to the adjoining cellar
- The garage end was knocked through into the taverna of the adjoining house, closed off by a door





## Cellar

**Before**



**After**



- Two cellars were knocked through
- The largest became the garage
- The smaller for the gas boiler and for wood storage etc

## Bathrooms

*First Floor*



*Ground Floor*



- Radiator, shower, sink, bidet, toilet

- Washing machine point
- Radiator, bath/shower, bidet, sink, toilet



**Exterior**

**Before**



**After**

